Historic Resources Survey City of McMinnville Yamhill County, Oregon

Si	ite Ir	nformatio	on						
Site Address O			Owner at T	ime of S	Survey				
414 NE Evans	St.			U.S.A.					
Map/Tax Lot		Current Zoning			Special Tax Assessment		Downtown Historic District		
R4421BC03200		C-3		No		Yes			
Subdivision Name					Lot	Lot Siz	Lot Size Qua		
Rowlands Addition					5	14,514	sq.ft. NE		
Site Number	e Number Aerial Number Resource Classificatio					Historic Significance			
17.35a	K-10 A			724	724 Secondary Resource #315				
Date of Constr 1930's		Early Addit		odels Builde Unkno		tect			
Historic Name Original Use					n Name		Present Us	e	
McMinnville Po Condition of S				McMinnv of Survey)	ville Post	Office	Post Office		
Excellent									
Building Type		Ou	Outbuildings		Building		S	Stories	
Public		No	ne				1		
Porch Baser	nent	Roof Style Flat		Roof Type		Moved	Demolished	Year/Date	
Permit Numbe	r(s)	Additions/	Alterations	5					
97B0772, 04B0 08B0298)794,	Interior Ren	nodel, Park	ing & ADA Ra	amp				
Reso	ourc	e Inform	ation						
Recorded By			Da	te	Source	S			
Wayne Belmont			8-1	980					

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

A724

The McMinnville Post Office is a square shaped, two-story structure (basement and one floor above ground) typical of many federal buildings, especially post offices built early in this century. The structure, which faces west on Evans Street, has a common bond brick exterior façade on all sides, and sets upon a cement foundation. The roof is flat and is topped by a brick parapet. An entablature, consisting of narrow segmented cement blocks over laying a wider cement frieze, rings the building two feet below the top. The fenestration on the front end (west) of the building is regular; two double-hung sash windows each with ten lights over fifteen are offset on each side of the main entrance. Plain cornice trims highlight the top of each window. The center door, main façade entrance, is detailed by a segmented arch opening; four fixed lights separated by ornate wood transoms over two large rectangular windows in the main door and two ornate pilasters. The entire doorway is constructed of wood. Landscaping appears to be original. The building is in excellent condition.

Historic Resource No. A724



Photo April 2001



Original 1983 Survey Photo