Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Information

Site Address		Owner at Time of Survey					
		da Weirich					
Map/Tax Lot Current 2		Special Tax Assessment			Downtown Historic District		
R4420DA01700 C-3		No		No	No		
		Block	Lot	Lot Siz	e Qu	adrant	
				8,472 s	sq.ft. SV	V	
Aerial Number Resource Classificati			Resource Number		Historic Significance		
	В	419		Secondary Resource #151			
Inform	ation	1					
2		Unkno	wn		Present U	lse	
Resid	dence				Residence	9	
ire Comm	nents (at time o	f Survey)					
Brokei	n gutters or dow	nspouts; In	need o	of paint.			
Outbuildings			Building Style		Stories		
Later Detached Garage		Garage	Square Bungalow		<u>'</u>	2	
_		Roof Type		Moved	Demolishe	ed Year/Date	
Addition	s/ Alterations						
-							
e Inforr	nation						
	Date		Source	es			
	Dato						
	ial Number Common Early Add Residure Common Broker Roof Style Medium Ga Addition	Current Zoning C-3 C-3 Cal Number Resource Classification B Cal Information Cal Early Additions/ Remode Classification B Cal Information Cal	Current Zoning C-3 C-3 No Block Resource Classification B Classification Cl	Current Zoning C-3 C-3 No Block Lot Special Tax Assessment No Block Lot Special Tax Assessment No Block Lot Special Tax Assessment No Block Resource Number A19 Classification B Later Detached Garage Additions/ Alterations Special Tax Assessment No Resource Number Number A19 Common Name Common Name Residence Common Name Residence Comments (at time of Survey) Broken gutters or downspouts; In need of Survey Additions/ Alterations Ce Information	Current Zoning Assessment C-3 No No Block Lot Lot Siz 8,472 s Sal Number Resource Classification B A19 Secondary Common Name Residence Resource Re	Current Zoning C-3 C-3 Block Block Lot Block Lot Size Qu 8,472 sq.ft. SV Assessment No Block Lot Size Qu 8,472 sq.ft. SV Assessment Builder/Architect Unknown Original Use Common Name Residence Residence	

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B419

A two story wood frame square bungalow with beveled siding. Medium gable roof with a second smaller gable on the façade. Part wood shingle in poor condition, part asbestos shingle. Full cement basement with north outside entrance. Some double hung windows with cornice moulding some casement. The off center gable roofed front porch has a central door with unbalanced window. Four pillars support porch roof. Steps and porch are of wood. There is a wood porch along back of house. Screens on all windows shut. Cement patio. Neat yard and landscaping. Center brick chimney.

Historic Resource No. B419



Original 1983 Survey Photo