Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Information

| Site Address | Own | wner at Time of Survey | | | | | | |
|---|--------------------------------|------------------------|----------------------------|---------|----------------------------|----------------------------|-------------|--|
| 1430 NE Evans Street | | | Michael & Margaret Dressel | | | | | |
| Map/Tax Lot Current Zoning | | ng | Special Tax Assessment | | | Downtown Historic District | | |
| R4416CC01000 R-4 | | | No | | No | No | | |
| Subdivision Name | | I | Block | Lot | Lot Siz | ze Qua | ndrant | |
| Beaumont Park Subdivision | | | 3 | 3 | 6,120 | sq.ft. NE | | |
| Site Number Aerial Number Resource Classification | | | Resour Numbe | | Historic S | istoric Significance | | |
| 22.13 K-9 | B | | 629 | | | | | |
| Historio | Information | | | | | | | |
| Date of Construction | n Early Additions/ R | emodels | Builde Unkno | | itect | | | |
| Historic Name | Original Use | С | Common Name | | | Present Use | | |
| S.S. Duncan House Residence | | | Residence | | | | | |
| Condition of Structu | re Comments (at t | ime of Su | rvey) | | | | | |
| Excellent | | | | | | | | |
| Building Type | ilding Type Outbuildings | | Building Style | | | Stories | | |
| Residential | None | | | Norm | an Farmhou | ise | | |
| Porch Basement □ ✓ | Roof Style Steep Pitched Gable | | f Type estos Sh | ningles | Moved | Demolished | d Year/Date | |
| Permit Number(s) | Additions/ Alterat | ions | | | | | | |
| 04B0693 | Fire damage repai | Fire damage repair | | | | | | |
| Resource | e Information | 1 | | | | | | |
| Recorded By | | Date | | Source | es | | | |
| Arlys Berry/Jean Dale | | 7-23-1980 | | | Dressel, Ow dams, neigh | | | |

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B629

Norman Farmhouse influence on beautifully landscaped lot. Much tender loving care on home.

Siding is wood shake with off-center entranceway stuccoed. Gabled hood over entry.

Roof of house is clipped gable, steeply pitched. One side slopes over attached single car garage. Shed dormer on south side. All roofs are of asbestos shingles. Walk way between garage and house is covered by continuous roof.

Complete cement basement with cement patio in rear. Center chimney and brick fireplace. Windows are double hung sash, some eight over eight.

Addition: Porch on back east side enclosed as part of kitchen. Cement step.

Historic Resource No. B629



Original 1983 Survey Photo