Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Information

Site	e intormat	tion						
Site Address			Owner at Time of Survey					
509 NE 9th Street		<u>L</u>	elanand Vi	ck Clee	k			
Map/Tax Lot Current		rent Zoning	Special Tax Assessment			Downtown Historic District		
R4421BB06200 R-3			No		No	No		
Subdivision Name			Block	Lot	Lot Siz	e Qua	adrant	
John's Addition			12	5	5,085 s	sq.ft. NE		
Site Number A	umber Aerial Number Resourd Classifi			Resource H Number		Historic Significance		
16.8 k	<-10	В	719	719 Primar		y Resource #310.1		
Histo Date of Construct	ric Inform	nation	als Ruilde	ar/∆rchi	tect			
ca. 1902 (1892)		site 1936	Unkno		lect			
Historic Name		inal Use	Common Name		Present Use			
Houck House Residence		dence		Residence				
Condition of Stru	cture Comr	ments (at time of	Survey)					
Good	In nee	ed of paint.						
Building Type Outbuilding		Outbuildings	Building Style			Stories		
Residential Attached one-		Attached one-car	r garge Rectangle			2		
Porch Basemer	nt Roof Style Gambrel	e R	loof Type		Moved	Demolishe	d Year/Date	
Permit Number(s) Additio	Additions/ Alterations						
Resou	rce Infor	mation						
			_	•				
Recorded By		Date		Source	es			
Janice Rutherford		8-17-1	1980					
- California								

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B719

This house originally belonged to the Houck Family of Houck Flouring Mills. It was moved to its present site in 1936 from the northwest corner of Eighth and Evans Streets.

It sits on a corner lot facing south. It is basically a rectangle, two stories, with a distinctive gambrel roof which has a pronounced flare on the lower slope and a cornice line at the break in slope. This line returns on the gambrel ends. A cross gambrel pavilion projects from the west elevation and a pedimented gable wall dormer from the west. In places the original siding of narrow V-grooved horizontal boards still shows but most of the house is covered by later cedar shingles. A flat roofed front porch which runs the width of the façade is substantially altered or added later; it has a concrete floor and steps and iron pipe supports. The foundation is covered by scored boards which simulate dressed stone. There is a basement.

Fenestration is fairly regular; windows are double hung. There are two bays; one on the first floor of the west elevation and one on the façade beneath the porch. The western bay is superimposed by a decorative balustrade under the second story window. Decorative shingles ornament the front and west gambrel ends as well as the gable over the garage.

The interior of the first floor retains most of the original woodwork with columns and paneling. The entry and dining room have unusual handsome panels of embossed leather and pressed copper. Ceilings in the entry, parlor, and dining room are decorated with plaster filigree in relief.

Historic Resource No. B719



Original 1983 Survey Photo