Historic Resources Survey City of McMinnville Yamhill County, Oregon

	ite Inf	ormat	ion						
Site Address			0	wner at T	ime of S	Survey			
441 NW 12th St.			N	Mikel F. Schutz					
Map/Tax Lot Current Zo R4417DD12901 R-1		Curi	Current Zoning		Special Tax Assessment		Downtown Historic District		
			No		No	No			
Subdivision N	ame			Block	Lot	Lot Size	e Qua	adrant	
Christensen's A	Addition			4	6	5,000 s	q.ft. NW		
Site Number Aerial Number Resource Classificatio		Resource Classification		Resource Histor Number		ric Significance			
1.9	I-9		В	73					
Hist	oric I	nform	ation						
Date of ConstructionEaca. 1920Historic Name			Original Use		Unknown Common Name		Present Use		
		Resi	dence				Single-fami	ly Dwelling	
			401100	-			enigie iain	., D	
Condition of S	tructure	Comn	nents (at time of	Survey)					
Condition of S	tructure		nents (at time of damage to porch		need of	paint.			
	tructure	Slight	-			paint. ng Style	S	Stories	
Good	tructure	Slight (damage to porch	steps; In	Buildi			Stories	
Good Building Type Residential Porch Baser	nent R	Slight (damage to porch Dutbuildings Detached Garage Greenhouse	steps; In	Buildi	ng Style ngular Bung	alow 1	Stories	
Good Building Type Residential	nent R	Slight (((((((((((((((((((damage to porch Dutbuildings Detached Garage Greenhouse	i steps; In	Buildi	ng Style ngular Bung	alow 1	1	
Good Building Type Residential Porch Baser ✓ □	nent R	Slight (((((((((((((((((((damage to porch Dutbuildings Detached Garage Greenhouse R	i steps; In	Buildi	ng Style ngular Bung	alow 1	1	
Good Building Type Residential Porch Baser ✓ □ Permit Numbe	nent R _L r(s)	Slight Coof Style ow Gable Addition	damage to porch Dutbuildings Detached Garage Greenhouse R	i steps; In	Buildi	ng Style ngular Bung	alow 1	1	
Good Building Type Residential Porch Baser ✓ □ Permit Numbe	nent R _L r(s)	Slight Coof Style ow Gable Addition	damage to porch Dutbuildings Detached Garage Greenhouse R Is/ Alterations	i steps; In	Buildi	ng Style ngular Bung Moved	alow 1	1	

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B73

This one-story rectangular bungalow has a south-facing, low-gabled roof with cornice boxed decorated returns. A secondary identical gable shelters an enclosed front porch over a row of six 6-lighted windows. There are identical bisecting gables on the east and west sides of the house as well. The gables have diamond-shaped, trellised air vents. The north side has a low hip roof and enclosed rear porch.

Weatherboarding, flared at the base, over a concrete foundation rises to approximately 5 ft. Above the weatherboarding, the finish is partially stuccoed vermiculated stone inlay. An exterior end chimney bisects the west gable.

Historic Resource No. B73



Photo October 2001



Original 1983 Survey Photo