

**Historic Resources Survey
City of McMinnville
Yamhill County, Oregon**

Site Information

Site Address

1034 NE Galloway St.

Owner at Time of Survey

Paul & Gloria Martinis

Map/Tax Lot

R4416CD12600

Current Zoning

R-3

Special Tax Assessment

No

Downtown Historic District

No

Subdivision Name

Oak Park Addition

Block

33

Lot

4

Lot Size

5,000 sq.ft.

Quadrant

NE

Site Number

21.33

Aerial Number

K-9

Resource Classification

A

Resource Number

668

Historic Significance

Primary Resource #274

Historic Information

Date of Construction

after 1890

Early Additions/ Remodels

Builder/Architect

Unknown

Historic Name

Original Use

Residence

Common Name

Present Use

Residence

Condition of Structure

Excellent

Comments (at time of Survey)

Building Type

Residential

Outbuildings

1 1/2 story garage

Building Style

Queen Ann

Stories

1

Porch

Basement

Roof Style

Hip

Roof Type

Moved

Demolished

Year/Date

1940's

Permit Number(s)

Additions/ Alterations

Resource Information

Recorded By

James K. Baird

Date

8-3-1980

Sources

Historic Resource Survey
City of McMinnville
Yamhill County, Oregon

Statement of historical significance and description of property:

A668

This one-story Queen Ann hip roof house with gabled bays has a flat-roofed (Mansard) cornice veranda which follows the various projections of the front elevation (west). A side (north) service porch is of similar design but within the main roof structure. The plan is near Latin cross yet the west bay is off-center to the south. The north and west bays have 45 degree corner angles with a single narrow double hung window in each. A wide double hung window is centered in each bay. Other windows are double hung (all single light) in irregular arrangement. The gable ends have boxed cornices with verge boards cut to form pointed arches. Within the walls are surfaced with cedar shingles in various patterns: i.e. fish scale, diamond, and straight. The roofing is also cedar shingle. The remainder is sided with six-inch drop siding with vertical boards below the watertable and porches.

The porches are highly detailed with a single balustrade and frieze stick work. They have turned supports with scroll cut brackets and wood flooring. A rear (east) door has a hip roof canopy of similar design. Door appears original and the windows have cornice molding.

The house is on a concrete foundation and is in excellent condition. A neighbor recalls that this house was moved from Fourth and Ford Streets in the mid-1940's.

Historic Resource No. A668



Photo July 2001



Original 1983 Survey Photo