## Historic Resources Survey City of McMinnville Yamhill County, Oregon

## Site Information

Site Address		Owner at T	Owner at Time of Survey				
1755 NW Baker Creek Rd.		Malcom Ma	Malcom Marsh & Willard Cushing				
Map/Tax Lot	p/Tax Lot Current Zoning		Special Tax Assessment		Downtown Historic District		
R4418 00100 County		No	No		No		
Subdivision Name		Block	Lot	Lot Siz	e Quad	lrant	
					NW		
Site Number Aerial Number Resource Classification					ignificance		
38.11, 38.12 G-6	B	10 (11	barn)				
Historic	Information						
Date of Construction	Early Additions/ Rem	nodels Builde	er/Archi	tect			
ca. 1880		Unkno	own				
Historic Name Original Use		Common Name			Present Use		
	Farm Residence				Farm Reside	ence	
Condition of Structure	e Comments (at time	e of Survey)					
Building Type	Outbuildings	<b>.</b>	Building Style		Stories		
Residential	Barn, Several	Others	ers Italianate Box		_2		
	Roof Style Flat Hipped	Roof Type	·	Moved	<b>Demolished</b> ✓	Year/Date	
Permit Number(s)	Additions/ Alteration	าร					
02B0183	Residential Demo						
Resource	Information						
Recorded By	Da	ate	Source	es			
Elizabeth Atly		2-1983					

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B10 1755 NW Baker Creek Road

This is a two story Italianate box, with flat hipped roof on paired decorative brackets and a wide frieze. Regular narrow 1/1 windows have architrave mouldings, and there is an Italianate bay window on the first floor east side. There are traces of a former porch on the center east side, a narrow central door over the first story door. Both doors have transoms and architrave mouldings. The upper has four lights and recessed panels, the lower has recessed panels only. Siding is novelty or drop siding with corner boards. The chimney is just off center. A one-story sloping gable roofed porch is attached at the rear and small shed is connected t this addition. Main house has a concrete foundation. The barn is a gambrel roofed dairy barn with board and batten siding. It is near collapse.

**BUIDING GONE BEFORE 2000** 

## Historic Resource No. B10(B11 Barn) Demolished 2002





Original 1983 Survey Photo