Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site	Information							
Site Address		Ov	Owner at Time of Survey					
235 NE Dunn Place	9	0.	E. & L.L. I	Full				
Map/Tax Lot Current Zoning		9				Downtown Historic District		
R4422CD01700	R-2 PD		No		No			
Subdivision Name			Block	Lot	Lot Siz	ze Qua	adrant	
Martin D.L.C.						NE		
Site Number A	erial Number Resource Classifica	-	Resour Number		Historic S	ignificance		
35.5a N-	13 <u>B</u>		1125					
Histor	ic Information							
Date of Constructi ca. 1890	on Early Additions/ Re	emodel	s Builde Unkno		tect			
Historic Name	Original Use	Original Use Co		ommon Name		Present Use		
	Residence	Residence		Lee Emary House		Residence		
Condition of Struc	ture Comments (at tir	me of S	Survey)					
Fair								
Building Type	Outbuilding	buildings		Building Style		Stories		
Residential	Sheds			Rural	Vernacular		1	
Porch Basement	Roof Style	Ro	of Type		Moved	Demolishe ✓	d Year/Date 4-16-199	
Permit Number(s)	Additions/ Alteration	ons						
99B0215	Burn to Learn							
9980215								
Resour	ce Information							
Recorded By	l l	Date		Source	S			
Vince Lowe		12-1983	3					

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B1125 – Demolished 1999

This one-story rural vernacular house has a greek cross plan and a cross-gable roof. The roof, a medium pitched gable, has boxed cornices, plain frieze, and simple moulding. A plain block interior chimney pierces the ridgeline. An Italianate bay window faces Three Mile Lane, as does a porch on turned posts on the west wing. The other porch on the east end consists of a hipped roof on plain 4×4 posts.

The roof has boxed cornices, plain frieze and simple moulding. The siding is horizontal "novelty" siding, with vertical siding or shingles in gables. Windows are typically one over one, with cornice moulding. The bay window has a hipped roof and vertical siding. There is no basement. The interior has been extensively remodeled.

The east section of this structure is a replacement of one which collapsed, according to the owner. The owner also states that a small outbuilding was originally used as a vegetable and fruit cellar.

Historic Resource No. B1024

Demolished 1999



Original 1983 Survey Photo