## Historic Resources Survey City of McMinnville Yamhill County, Oregon

				Sounty, Or	egon				
Si	ite In	format	ion						
Site Address				Owner at T	ime of S	urvey			
228 NW 7th Sti	reet			Bernard & I	Rosalind	Turner			
Map/Tax Lot		Current Zoning			Special Tax Assessment		Downtown Historic District		
R4420AD01000		R-2		No	No		No		
Subdivision Name				Block	Lot	Lot Siz	e Quad	Irant	
Baker & Martin's Subdivision				15	4	6,265 s	q.ft. NW		
			Resource Classificati		Resource Historic Significance Number				
7.9a	J-10		В	289					
Hist	toric	Inform	ation						
ca. 1935-40 Historic Name Mattechek House Condition of Structure		Original Use Single Family Residence Comments (at time of		Commo	Unknown Common Name Turner House		Present Use Single Family Residence		
	in ucture		·	e or Survey)					
Good Building Type		In need of paint. Outbuildings			Building		ityle Stories		
Residential		None				<b>J</b> - <b>y</b> -	1.		
Porch Baser	ment	Roof Style		Roof Type		Moved	Demolished		
Permit Numbe	er(s)	Addition	s/ Alteration	S					
07B0214		Interior F	Residential Re	emodel					
Reso	ource	e Inforr	nation						
Recorded By			Da	ite	Source	S			
Samuel C. Lowry	y		7-1	1980					

## Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

## B289

This is a medium sized, 1 ½ story dwelling of wood-frame construction, incorporating a variety of stylistic features. The main roof line is oriented north-south, gabled at both ends. The southern gable is of the "bellcast" type, flaring outward over the garage to the east, and over an enclosed, glassed in porch to the west. The front gable flares only at the western and, over the front door porch. The upper portion of each end gable provides several inches beyond the lower portion. The western elevation is entirely different, faced with brick, with a rounded bay window and a "Tudor" style stick-and-stucco pediment above a bracketed cornice. On the eastern side, the steep-pitched roof drops directly into the overhanging porch roof. Windows are generally of the sash type with six or more lights of one. There is a hexagonal, hipped-roofed bay window on the north side. This house is in very good state of preservation, and appears virtually unchanged from its original appearance. The house was built for the Mattachek family.

## Historic Resource No. B289



Original 1983 Survey Photo