Historic Resources Survey City of McMinnville Yamhill County, Oregon

			Yamhill C	oun	ty, Ore	egon				
Sit	e Inf	ormati	on							
Site Address				Ow	ner at Ti	ime of S	Survey			
1320 SW 2nd St.				Pat	rick & Da	arlinda H	lamil			
Map/Tax Lot		Current Zoning			Special Tax Assessment		Downtown Historic District			С
R4420CA03501					No		No			
Subdivision Nar	ne				Block	Lot	Lot Siz	e	Quad	rant
Slusher-Davis Ac	dition					2	10,000	sq.ft.	SW	
Site Number Aerial Number Resource Classification				on	Resource H Number		Historic Si	Historic Significance		
31.39	H-11		В		32					
Histo	oric I	nform	ation							
Historic Name	ucture	Resid	nal Use ence ents (at time		Commor urvey)				ent Use dence	
Building Type		Outbuildings				Building Style		Stories		
Residential		None				Latin Cross		2		
Porch Baseme		Roof Style High Gable		Roo	of Type		Moved	Demo	olished	Year/Date
Permit Number(s)	Addition	s/ Alteration	S						
05B0398 06B0955, 09B03	94	Repair fo New Gara	undation, age, Entrywa	y Ado	lition					
Reso	urce	Inforn	nation							
Recorded By			Da	ite		Source	S			
Vince Lowe			12	-1983						

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B32

Resident says former owner, now deceased, told her the house was built by a retired sea captain for his young bride. A section was added in 1940, as an apartment. The house was further remodeled and converted into a retirement home. A fireplace was added in the 1950's. The exterior retains its integrity despite interior alterations.

The house is Latin cross shaped with a high gable roof which has boxed cornices, wide frieze and moulding. The house is sheathed in wide drop siding with cornerboards. Gables have fish scale shingles down to the top of paired second story windows. Windows are typically 1/1 double hung sash. On single windows, a small pediment tops the otherwise plain moulding. There are Italianate bay windows in the north and east sides with hip roof supported on ornate small consoles and a frieze with recessed panels. A small front stoop has hip roof supported on turned decorative posts with open spooled lintel and decorative bracket. The porch has a wood rail and ornate balustrade.

Historic Resource No. B32



Photo October 2001



Original 1983 Survey Photo