Historic Resources Survey City of McMinnville Yamhill County, Oregon

				bunty, Or	egon				
	Site	nformat	ion						
Site Ad	ldress			Owner at T	ime of S	Survey			
131 NE	5th Street			H.S. & Mad	eline O'd	lell			
Map/Tax Lot Cu		Cur	Current Zoning		Special Tax Assessment		Downtown Historic District		
R4420AD03200		C-3	<u>C-3</u>		No		No		
Subdivision Name				Block	Lot	Lot Size	e Qua	drant	
						5,278 sc	q.ft. NE		
Site Number Aerial Num		ial Number	nber Resource Res Classification Nur			Historic Siç	toric Significance		
6.9	<u>J-10</u> B		332	<u>Seconc</u>		dary Resource #85			
	Histori	c Inform	ation						
Between 1912-1928 Historic Name		Resident Orig	Early Additions/ Remodel Residential Addition/Garage Original Use Residence				Present Use Residence		
Conditi	ion of Struct		nents (at time		0030		Tresidence		
Excelle	ent								
Buildin	ід Туре	(Outbuildings		Building Style		Stories		
Residential			None		Bunga	low	2		
Porch ✓	Basement ✓	Roof Style Bellcast Ga		Roof Type		Moved	Demolished	Year/Date	
Permit Number(s)		Addition	s/ Alterations						
00B0332, 11B0487		•	Replace Covered Porch/Stain Fire Damage Repair						
	Resour	ce Infor	nation						
Recorded By			Dat	e	Source	S			
Marietta Rankin			5-5-1980		Sanborne Maps 1912, p. 7; 1928, p. 10				

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B332

A two-story bungalow with bellcast gable roof with roof brackets under rake two gable dormers with brackets under rake. Each dormer has two double-hung sash windows with cornice moulding. A bay on the west side has three windows, one over one double-hung sash. The front window is protected.

The basement is half daylight with wood water table. The siding is bevel with corner boards. There is a central chimney. The entrance is within a gabled off-center porch. The door is a full window with full length side lights. The porch gable is decorated with vertical boards and stucco, to simulate half timbering. A flat-roofed attached garage may have been added later. A harmonious addition to the back of the house was done in 1940 by Bill Odell. The dining room ceiling has exposed wood beams.

Historic Resource No. B332



Original 1983 Survey Photo