Historic Resources Survey City of McMinnville Yamhill County, Oregon

| | | Yamhill Cou | nty, Ore | egon | | | | |
|---|---------------------|------------------|---------------------------|--|-------------------------------|-------------------------------|-----------|--|
| Site In | format | ion | | | | | | |
| Site Address | | 01 | wner at Ti | ime of S | Survey | | | |
| 345 SW Baker Street | | C | olena And | erson | | | | |
| Map/Tax Lot Curre | | ent Zoning | Special Tax Assessment | | _ | Downtown Historic District | | |
| R4420DA01900 | 01900 C-3 | | No | | No | No | | |
| Subdivision Name | | | Block | Lot | Lot Size | e Quad | rant | |
| Original Town | | | | | | SW | | |
| Site Number Aerial Number Resource Classification | | | | Resource Historic Significance Number | | | | |
| 9.10 J-11 | -11 <u>B</u> | | 421 | 21 Primary | | Resource #153 | | |
| Date of Construction ca. 1908 | Early Add | litions/ Remode | Is Builde Unkno | | itect | | | |
| | | | | | | | | |
| Historic Name | Origi | nal Use | Commor | n Name | • | Present Use | | |
| Jones House Residence | | lence | Residence | | | | | |
| Condition of Structur | e Comm | ents (at time of | Survey) | | | | | |
| Excellent | | | | | | | | |
| Building Type | | Outbuildings | ldings Buildi | | ing Style | g Style Stories | | |
| Residential None | | lone | | Bunga | alow | 1. | 5 | |
| Porch Basement ✓ □ | Roof Style Gable | - | | of Type | | Demolished | Year/Date | |
| Permit Number(s) | Addition | s/ Alterations | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Resource | e Inforn | nation | | | | | | |
| Recorded By | | Date | - | Source | es | | | |
| Arlys Berry & Jean Dale | | 6-17-19 | 980 | | Anderson, ow n Map 1912, p | | | |

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B421

The house is a well kept bungalow with beveled wooden siding. Cement steps lead up to front porch, which extends across front of the house. There are four wooden pillars set on brick and iron railings lead to porch. There is a center door on the main façade. The roof is a many bracketed gable covered with new asbestos shingles. There is an added back patio and covered arbor in rear. On the front of house is a four window shed dormer. The window treatment is some casement and some double hung sash with plain trim. There is a projecting bay on the north side with a large double hung sash. Also on north side is an outside cellar door. The landscaping is lovely and extends though the block to the rear to Adams Street.

The original owner was C.B. Jones.

Historic Resource No. B421



Original 1983 Survey Photo