Historic Resources Survey City of McMinnville Yamhill County, Oregon

S	ite Ir	nformat	ion							
Site Address				Own	Owner at Time of Survey					
206 NE Cowls	Street			Ralp	h Shoo	f				
Map/Tax Lot		Current Zoning			Special Tax Assessment		Downtown Historic District			
R4421BC08800		C-3			No	10		Yes		
Subdivision Name				Block	Lot	Lot Siz	e Qua	drant		
Original Town					13	5		NE		
Site Number Aerial		al Number	Number Resource Classification		Resource Number		Historic Significance			
8.25a	a <u>J-11 B</u>		В		451 Second		Secondary	ry Resource #174		
		Inform			Duilde		11			
Date of Const 1920	ruction	Early Ad	ditions/ Rem	iodeis	Unkno		tect			
Historic Name		Original Use		С	Common Name			Present Use		
Home Laundry		Laundry		<u>H</u>	Home Laundry			Laundry		
Condition of S	Structu	re Comn	nents (at tim	e of Sı	ırvey)					
Building Type		Outbuildings		5		Building Style		Stories		
Commercial		None			Spanish Revival					
Porch Basement		Roof Style R		Roo	f Type		Moved	Demolished ✓	Year/Date 1995	
Permit Numbe	er(s)		s/ Alteration	າຣ					1000	
	(0)	, laanier								
Reso	ourc	e Inforr	nation							
Recorded By		Date		ate		Source	S			
Janice Rutherfor	Janice Rutherford		6-	·18-198()	Curt Shumate, owner; Photograph, Fire Dept. Files				

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B451 – Demolished 1995

Home Laundry, built in 1920 by Rudolph H. Windishar, its first owner, has had only three owners since birth. The facility began using a woodburning boiler, the yearly supply of fuel for which covered an entire half block. It has since converted to oil. Second owner of the business was Ralph Schoof, who still owns the building. In 1975 the business was purchased by its present operator, Curtis D. Schumate.

The structure essentially is a solid stucco-covered brick, flat-roofed square of one story in the Spanish revival style. An off-center pyramidal-roofed tower (originally tile-roofed) rises to the right of the west-façade and masks a partial second-story which runs the length of the building behind it. The Spanish tile remains at the roof line and on the pentroof over the original entrance, two large inset arched windows are now boarded over. The façade originally had four unevenly spaced arched openings; two have been converted to rectangular windows. Fenestration on the side elevations is irregular with varying sizes of multi-lighted windows. The building is one of few of this style in the city and has under gone little change.

Historic Resource No. B449

Demolished 1995



Original 1983 Survey Photo