Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Information

Site Address Ow			wner at Time of Survey				
344 SW Bills Street		Gladys Wer	Gladys Wendling & Betty Hyde				
Map/Tax Lot Current Zonin		•	Special Tax Assessment		Downtown Historic District		
R4420DA07700 R-2		No	No		No		
Subdivision Name		Block	Lot	Lot Size	e Quad	rant	
Cozine's 2nd Addition			18	5,629 sc	q.ft. SW		
Site Number Aerial Number Resource Classific			Resource Historic Si Number			gnificance	
16.5 J-12	B	498	8 Primary Re		esource #212		
Historic	Information						
Date of Construction	Early Additions/ Rei			ect			
ca. 1900		Unkno	own				
Historic Name Original Use		Commo	Common Name Present Use				
	Residence				Residence		
Condition of Structure Comments (at time of Survey) Small cracks in walls/chimney; Missing material (foun/steps); Deep wear on stairs; Poor foundation (back); Sagging walls/ roof.							
Building Type	Outbuilding	ıs	Buildin	g Style	Stories		
Residential	None		Square		2		
Porch Basement ✓	Roof Style Cross Gable	Roof Type		Moved	Demolished	Year/Date	
Permit Number(s)	Additions/ Alteration	ons					
Resource Information							
Recorded By		Date	Sources	i			
Carrie Carlile		7-1980					

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B498

This house is a two-story wood frame construction with concrete foundation. The roof is cross gabled with returns, the main part being a truncated hip type. The windows are tall, narrow and double hung, one light over one. The two porches, one north in front of the house, and one east, have one-story hipped roofs, wooden floors and steps, and plain round wooden posts. The house is basically square, but has a one-story back extension with hipped roof. There is a gabled extension off of that which appears to have only wooden blocks under it for foundation support. It is sagging and shows much more age, due to its construction features, than the main part of the house.

There are two chimneys rising from the center of the house, and one from the gabled extension in the rear. The house has plain corner boards and frieze boards.

Historic Resource No. B498



Original 1983 Survey Photo