Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Information

Site Address			Ow	Owner at Time of Survey						
1015 NW Baker	Creek Ln.		H.P	. Mahon	/A.K. Ma	ahon				
Map/Tax Lot Current Zor		Current Zonin	ng		ial Tax ssment	Downtown Historic District				
R4417BA08600 R-1			No		No					
Subdivision Nar	me			Block	Lot	Lot Siz	e	Quad	rant	
Norwegian Wood Subdivision					4	40,142	40,142 sq.ft. NW			
Site Number Aerial Number Resour			Resource F Number		Historic Significance					
31.9	I-6	<u>B</u>		50						
Histo	oric Info	rmation								
Date of Construction ca. 1915-20	ction Earl	y Additions/ R	emodels	Builde		tect				
Historic Name		Original Use Comm		Commo	n Name		Prese	ent Use		
		Farm Residence	ce				Farm	Reside	nce	
0 1141 604										
Condition of Str	ucture C	Comments (at t	time of S	urvey)						
Building Type	ructure C	Comments (at t		urvey)	Buildi	ng Style		Sto	ories	
	ructure C			urvey)	Buildi Box	ng Style		Sto 2	ories	
Building Type	ent Roof	Outbuildir None	ngs	of Type			Demo	2	ories Year/Date	
Building Type Residential Porch Baseme	ent Roof	Outbuildir None Style	ngs Roc			Moved	Demo	2		
Building Type Residential Porch Baseme	ent Roof Mediu s) Add	Outbuildir None Style Im Gable	ngs Roc			Moved	Demo	2		
Building Type Residential Porch Basem Permit Number(07B0651	ent Roof Mediu s) Add	Outbuildir None Style Im Gable ditions/ Alterat	ngs Roc ions			Moved	Demo	2		
Building Type Residential Porch Basem Permit Number(07B0651	ent Roof Mediu s) Add	Outbuildir None Style Im Gable ditions/ Alterateset Garage	ngs Roc ions			Moved	Demo	2		

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B50

This two-story box has craftsman bungalow detailing. It has a medium gable roof with an east facing dormer (the house is oriented north/south). The south facing entry porch is on the west side of the façade and has a gable pediment roof with exposed beams and rafters and medium wide vergeboards, resting on square columns with recessed bevels. The porch has open railing. Stair rails are wrought iron. Window sash are typically 6/6 double hung. There is a three-window bay with shed roof to the east of the entry porch. The upstairs windows have shutters. Siding on the first floor is clapboard; above are wide cedar shingles. A belt course separates them. The gables are stucco and half-timber. There is a recent addition of narrow brick facing on the lower west side. There is a wide shed roof porch on the east side with double doors. Its detailing is similar to the south porch. On the rear of the north side is a windowed second story sleeping porch with unusually wide overhanging eaves.

The massing of this house is imposing. The cross gables are wide and deep and rise a full two and one-half stories. The chimney is just off center.

Historic Resource No. B50



Original 1983 Survey Photo