Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Information

Site Address			Owner at Time of Survey					
1200 NW Michelbook Lane		Mic	Michelbook Estates, Inc.					
Map/Tax Lot Current Zoning		9	-	ial Tax ssment		Downtown Historic District		
R4417 01503 R-1			No		No	No		
Subdivision Name			Block	Lot	Lot Siz	e Qua	drant	
					97 acr	es NW		
Site Number Aerial Number Resource Classificati		_	Resource H Number		Historic S	listoric Significance		
1.23 I-9	B		56					
Historio	Information							
Date of Construction ca. 1930	Early Additions/ Re	models	Builde Unkno		itect			
Historic Name	Original Use		Common Name			Present Use		
Residence			Michelbook House			e Residence		
Condition of Structu	re Comments (at ti	me of S	urvey)					
Excellent								
Building Type	Outbuildings		Building		ing Style	tyle Stories		
Residential	None		Colonial			2		
Porch Basement ✓ □	Roof Style Low Gable		Roof Type Composition		Moved ✓	Demolished	Year/Date 1991	
Permit Number(s)	Additions/ Alterations							
2-3-91, 2-4-91, 6-52-91 (Linfield Ave.)	Move house to 450 SW Linfield Ave., New Foundation, Complete move setup - Commercial Remodel (Linfield Ave.)							
Resourc	e Information							
Recorded By		Date		Source	es			
Beth Westford		9-1983						

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B56 (Moved to 450 SW Linfield Avenue - 1991)

Spectacular landscaping dominates the Colonial style two-story structure which has a central block with one wing. The house is situated on an oversized lot facing east which includes numerous massive evergreen, oak and walnut trees.

The low gabled roof has corniced box plain returns on the north and south. The asymmetrically placed frontispiece northeast entrance has an arched opening with semi-elliptical fanlight and three-light top half sidelights framing a six-panel single door with hood mould. The brick walk step porch is semi circular with a wrought iron railing. There is a 15-light central entry on the south off a large brick porch with wrought iron railing.

The north side has a two-story bay off the central block with gabled roof and corniced boxed return. There is also an attached carport with shed roof. There is a combination of window types as follows: first floor east—40-light and 32-light windows; second floor—6/12/6 three-panel (side panels inward opening casement), also two 6/6 double hung sash windows; second floor west—21-light windows; north side—a gothic sash window with hood mould placed between stories and 6/6 double hung sash windows.

The house is in an excellent state of preservation. The exterior siding is weatherboarding; the foundation is concrete; and the roof is composition shingle. The interior brick chimney has three pots with spine moulding.

Historic Resource No. B56 (moved to 450 SW Linfield Ave. – 1991)



Photo October 2001



Original 1983 Survey Photo