Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Information

		Tormat								
Site Address				O	Owner at Time of Survey					
436 NE Galloway Street				R	.A. & Kathryn Wyffels					
Map/Tax Lot		Current Zoning		g	Special Tax Assessment		Downtown Historic District			
R4421BD02800		C-3			No		No			
Subdivision Na	ame				Block	Lot	Lot Siz	e Qua	drant	
Rowland's Addition					9	3		NE		
Site Number Aerial N		Number Resource Classification		_	Resource H Number		Historic S	Historic Significance		
18.12	K-10		В		764		Secondary	Secondary Resource #348		
Hist	oric	Inform	ation							
Data of Constru		Forty Ad	ditional Da	! .	i Duild	o u / A u o lo !	44			
Date of Constr ca. 1920	uction	Early Ad	ditions/ Re	emode	Unkno		tect			
Historic Name		Original Use			Commo	Common Name Present Use			е	
		Residence			-	Apartmen				
Condition of S	tructure	e Comm	nents (at ti	me of	Survey)					
Good										
Building Type		Outbuildings			Building Style		Stories			
Residential		None			Bungalow		v1.5			
Porch Basen ✓		Roof Style Hip		R	oof Type		Moved	Demolished	Year/Date	
Permit Number	r(s)	Addition	s/ Alteration	ons						
02B0535		Repl. exi	sting deck	stairs						
Resc	nurce	Inforr	nation							
	Juice	<i>,</i> 1111011				C	_			
Recorded By				Date		Source	95			
Arlys Berry Jean Dale				7-3-19	9 0					
Jean Dale				1-3-19	OU					

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B764

Typical bungalow house made into four or five apartments. Gabled asbestos shingle roofs with wide overhang and wall dormers. Hipped roof over front porch, front porch is off-center with heavy columns resting on stone piers, wood steps. Old front door with benched glass. Double hung sash window with cornice moulding; fixed windows with cornice moulding. Decorative brackets and exposed rafters. There is an outside stone chimney and inside central stone chimney. Cored siding. Two north side entrances; one to first floor, one to stone and cement basement. Back, east side has two entrances and outside stairway to second floor.

Historic Resource No. B764



Original 1983 Survey Photo