# Historic Resources Survey City of McMinnville Yamhill County, Oregon

# **Site Information**

Site Address	O	Owner at Time of Survey						
715 NE 5th Street		Cl	narles & L	inda Wh	itney			
Map/Tax Lot Current Zon		t Zoning	Special Tax Assessment			Downtown Historic District		
R4421BA09500 O-R			No		No			
Subdivision Name			Block	Lot	Lot Siz	e Q	uadrant	
Oak Park Addition					6,000 s	q.ft. N	<u> </u>	
Site Number Aerial Number Resource Classifica		Resource Classification	Resource Histo Number		Historic Si	toric Significance		
18.9 K-10	0 <u>B</u>		767 Primar		Primary Re	ry Resource #350		
Historio	Informa	tion						
Date of Construction prior to 1909	n Early Addit	ions/ Remode	Builde		ect			
Historic Name Original Use		I Use	Common Name			Present Use		
Residence						Residence		
Condition of Structu	re Commer	nts (at time of	Survey)					
Excellent								
Building Type Outbuilding		tbuildings	Building Style			le Stories		
Residential	Ga	rage		Square	e Shaped		2	
Porch Basement ✓	Roof Style Cross Gable		Roof Type Asphalt Shin		Moved	<b>Demolished</b>	ed Year/Date	
Permit Number(s)		Alterations	•	<u> </u>	_			
13B0496	Enclose ga	rage						
Resourc	e Inform	ation						
Recorded By		Date	4	Source	S			
Jean Dale/Arlys Berry		7-21-19	980	Don & R	osemary Tro	oxel		

### Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

#### B767

This two-story, basically square-shaped home has a cross gable roof of asphalt shingles with a pediment dormer. The siding is coved, the foundation is cement. There is a full basement with outside cellar steps on the west side.

The window treatment is double hung sash with shelf, front leaded. On the west side are two projected squares with decorative brackets enclosing large windows. There is a one pillared front porch with an off center oblong glass door with beautiful brass hardware. The brass doorknobs are throughout the house.

There is a small rear porch enclosed with cross slats. Single car garage. One center brick chimney.

The yard is nicely landscaped and enclosed with a chain link fence.

The property at one time was adjacent to where the Catholic Church stood. The present owner's son, while digging in the yard, discovered old wine, whiskey, and ale bottles which had been buried in rose about three feet down by the priests. Over 300 bottles have been found so far.

## **Historic Resource No. B767**



Original 1983 Survey Photo