Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Information

Site Address O		Owner at Ti	wner at Time of Survey				
915 NE Lafayette Avenue		J.E. & Doris	J.E. & Doris Davenport				
Map/Tax Lot	Lot Current Zoning		Special Tax Assessment		Downtown Historic District		
R4421BA02700	R4421BA02700 C-3		No No				
Subdivision Name		Block	Lot	Lot Siz	e Qua	adrant	
Oak Park Addition		4	1	5,000 s	q.ft. NE		
Site Number Aerial Number Resource Classifica			Resource Historic Significance Number				
19.14 K-10	<u>B</u>	822	822 Primary Resou		source #370	urce #370	
	Information						
Date of Construction	Early Additions/ Rem			ect			
ca. 1900		Unknown					
Historic Name	Original Use	Commoi	n Name		Present Us	Se	
	Residence		Resid			dence	
Condition of Structure Comments (at time of Survey)							
Good	Broken gutters or c	downspouts; In	need of p	oaint.			
Building Type	Outbuildings	5	Building		Style Stories		
Residential	None		Vernacular/Victorian			2	
Porch Basement ✓	Roof Style Medium Gable	Roof Type		Moved	Demolishe ✓	d Year/Date 2000	
Permit Number(s)	Additions/ Alteration	าร					
00B0231	Residential demo			_			
Resourc	e Information						
Recorded By	Di	ate	Sources	i			
Samuel C. Lowry	8-	-3-1980					

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B822 – Demolished 2000

This is a large two-story wood frame house of a vernacular design with many elements of Victorian styles. In particular, the lofty and somewhat grand impression it gives hearkens to Victorian architecture. The floor plan is in the form of a "T", with the tail of the "T" pointing southwest. The roof is a medium gable, with gabled ends facing southwest, northwest, and southeast at each point of the T. The front elevation contains the main entrance, off-center beneath a shed roofed porch supported on 4" x 4" wooden posts. Above this is an overhanging, gabled square bay with broad rake boards and returns, identical to the main gable on a smaller façade. The rear elevation contains the same proportionate gable and gabled bay. There are two smaller, one story gables at the northern corner and a large shed-roofed dormer. Windows throughout are tall, double hung with one-over-one, and with heavy top cornices, in harmony with the loftiness of the structure. This house is a very well preserved example of a fairly simple Victorian style, preserving most of the original materials and design elements.

Historic Resource No. B822 Demolished 2000



Original 1983 Survey Photo