## Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Information						
Site Address		O٧				
619 NE 3rd Street		Fra				
Map/Tax Lot	Current Zoning					

wner at Time of Survey

619 NE 3rd Str	Fi	Francis B. Fenton						
Map/Tax Lot	Cui	Current Zoning		Special Tax Assessment		Downtown Historic District		
R4421BC0430	0 <u>C-3</u>		Yes		Yes			
Subdivision N	ame		Block	Lot	Lot Size	Quadrant		
Rowland's Add	lition		7	3		NE		
Site Number	Aerial Number	Resource Classification	Resource H Number		Historic Signifi	Historic Significance		
11.32	K-11	В	872		Secondary Resource #435			

## **Historic Information**

Date of Construction 1912-1928	Early Additions/ Remodels Builder/Architect Unknown							
Historic Name	Original Use Common Name			Present Use				
	Commercial	News Register Building			Newspaper Office			
Condition of Structure	e Comments (at time of Survey)							
Good								
Building Type	Outbuildings		Building Style		Stories			
Commercial	Attached Buildi	ng to Rear	Square		2			
Porch Basement F	Roof Style	Roof Type		Moved	Demolished	Year/Date		
Permit Number(s)	Additions/ Alterations							
99B0561; 05B0231; 06B0830	Add 2 new awnings; Int'r commercial rem'l			_				
Resource	Information							
Recorded By	Date	e	Sources					
Janice Rutherford	7-19	80	Sanborn M	1aps, 1912	2-1928			

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

B872 State Special Assessment Program

This is a square brick two story structure situated middle block between Ford and Galloway facing south on Third Street. The façade is five bayed, the second story windows being one over one double hung sash, paired, each pair articulated by rows of stretchers. A prominent bracketed and modillioned cornice line stretches the length of the façade above these windows. A parapet wall with a central gable rises three feet above the cornice line. The façade is faced with common bond buff brick above the first floor. Extensively altered, the first story of the façade is faced with scored stucco and ahs been cutaway to expose two pillars. A stairwell opens onto the street at the extreme east end. The building has been joined to another at its rear which faces Fourth Street on the north. In 1928, the building housed a garage.

## Historic Resource No. B872



Original 1983 Survey Photo